

AD-A102 671

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/6 13/13  
NATIONAL DAM SAFETY PROGRAM. LAKE OCQUITTUNK DAM (NJ00260), DEL--ETC(U)  
JUL 81 A PERERA DAC#61-79-C-0011

DAEN/NAP-53842/NJ00260-81/ NL

UNCLASSIFIED

1 09 |  
AD-A  
10 26 71

END  
DATE  
FILMED  
9-81  
DTIC

LEVEL



AD A 102671

DELAWARE RIVER BASIN  
BIG FLAT BROOK, SUSSEX COUNTY  
NEW JERSEY

# LAKE OCQUITTUNK NJ 00260

## PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



THIS DOCUMENT IS UNCLASSIFIED  
IN WHOLE OR IN PART IN ACCORDANCE WITH  
E.O. 13526, WHERE PRACTICABLE.  
THE COPY FURNISHED TO DDC CONTAINED A  
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.

REPRODUCED FOR PUBLIC RELEASE  
DISTRIBUTION UNLIMITED.

DEPARTMENT OF THE ARMY DTIC

Philadelphia District  
Corps of Engineers  
Philadelphia, Pennsylvania



ELECTE  
AUG 11 1981

REPT. NO: DAEN/NAP-53842/NJ-00260-81/07<sup>D</sup>

JULY 1981

DTIC FILE COPY

81 8 10 099

**NOTICE**

**THIS DOCUMENT HAS BEEN REPRODUCED  
FROM THE BEST COPY FURNISHED US BY  
THE SPONSORING AGENCY. ALTHOUGH IT  
IS RECOGNIZED THAT CERTAIN PORTIONS  
ARE ILLEGIBLE, IT IS BEING RELEASED  
IN THE INTEREST OF MAKING AVAILABLE  
AS MUCH INFORMATION AS POSSIBLE.**

## **DISCLAIMER NOTICE**


**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

National Dam Safety Program. Lake Ocquittunk Dam (NJ00260), Delaware River Basin, Big Flat Brook, Sussex County, New Jersey. Phase 1 Inspection Report.

SECURITY CLASSIFICATION OF THIS PAGE (When Data Ent)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER DAEN/NAP-53842/NJ00260-81/07	2. GOVT ACCESSION NO. AD-A102671	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program Lake Ocquittunk Dam, NJ00260 Sussex County, NJ	5. TYPE OF REPORT & PERIOD COVERED FINAL	
	6. PERFORMING ORG. REPORT NUMBER	
7. AUTHOR(s) Perera, Abraham P.E.	8. CONTRACT OR GRANT NUMBER(s) DACW61-79-C-0011	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Louis Berger Assoc. 100 Halstead St. East Orange, NJ 07019	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS NJ Department of Environmental Protection Division of Water Resources P.O. Box CNO29 Trenton, NJ 08625	12. REPORT DATE July, 1981	
	13. NUMBER OF PAGES 50	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, PA 19106	15. SECURITY CLASS. (of this report) Unclassified	
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams National Dam Safety Program Spillways Embankments Lake Ocquittunk Dam, NJ Erosion Visual Inspection Big Flat Brook, NJ Inlets Structural Analysis Delaware River Basin		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



DEPARTMENT OF THE ARMY  
 PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
 CUSTOM HOUSE-2 D & CHESTNUT STREETS  
 PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO  
 NABEN-N

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
PTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Avail and/or	
Dist	Special
A	23 CP

Honorable Brendan T. Byrne  
 Governor of New Jersey  
 Trenton, New Jersey 08621

DTIC  
 ELECTRIC  
 AUG 11 1981  
 S D D

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Lake Ocquittunk Dam, Sussex County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Lake Ocquittunk Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in good overall condition and the spillways are considered adequate. To ensure the adequacy of the structure the following remedial actions are recommended:

- a. Remove the silt from the pond and low-level drain outlet pipe within thirty days from the date of approval of this report.
- b. The following remedial actions should be initiated within one year from the date of approval of this report:
  - (1) Clear the brush and trees from the embankment and the upstream face of the dam as well as the dike.
  - (2) Monitor the seepage between the spillway and drain outlets.
  - (3) Fill, grade, and reseed the eroded area at the sides of the low level drain and repair the wave cut bench on the upstream face.
  - (4) Inspect, repair, and test the valve for the drain.
  - (5) Inspect and repoint the masonry sidewalls of the drop inlet spillway and channel where necessary.

APPROVED FOR PUBLIC RELEASE;  
 DISTRIBUTION UNLIMITED.

NAPEN-N


Honorable Brendan T. Byrne

A copy of the report is being furnished to Mr. Dirk C. Holman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Courter of the Thirteenth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



ROGER L. BALDWIN  
Lieutenant Colonel, Corps of Engineers  
Commander and District Engineer

1 Incl  
As stated

Copies furnished:

Mr. Dirk C. Holman, P.E., Deputy Director  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CNO29  
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief  
Bureau of Flood Plain Regulation  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CNO29  
Trenton, NJ 08625

LAKE OCQUITTUNK DAM (NJ00260)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 16 January and 5 February 1981 by Louis Berger and Associates, Inc., under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Lake Ocquittunk Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in good overall condition and the spillways are considered adequate. To ensure the adequacy of the structure the following remedial actions are recommended:

a. Remove the silt from the pond and low-level drain outlet pipe within thirty days from the date of approval of this report.

b. The following remedial actions should be initiated within one year from the date of approval of this report:

(1) Clear the brush and trees from the embankment and the upstream face of the dam as well as the dike.

(2) Monitor the seepage between the spillway and drain outlets.

(3) Fill, grade, and reseed the eroded area at the sides of the low level drain and repair the wave cut bench on the upstream face.

(4) Inspect, repair, and test the valve for the drain.

(5) Inspect and repoint the masonry sidewalls of the drop inlet spillway and channel where necessary.

APPROVED:



ROGER L. BALDWIN  
Lieutenant Colonel, Corps of Engineers  
Commander and District Engineer

DATE:

27 July 81

D E A E E

DELAWARE RIVER  
BASIN

Name of Dam: Lake Ocquittunk  
County and State: Sussex, New Jersey  
Inventory Number: NJ 00260

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

Prepared by: Louis Berger & Associates, Inc.  
For: State of New Jersey  
Department of Environmental Protection  
Date: 22 May 1981

Report Cover Color Code: Yellow



OVERVIEW OF LAKE OCQUITTUNK DAM  
MARCH, 1991

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

Name of Dam Lake Ocquittunk Dam Fed ID# NJ 00260

State Located New Jersey  
County Located Sussex  
Coordinates Lat. 4113.6 - Long. 7445.8  
Stream Big Flat Brook  
Date of Inspection January 16 and February 5, 1981

ASSESSMENT OF  
GENERAL CONDITIONS

Lake Ocquittunk Dam is considered to be in a generally good condition and has a spillway capacity adequate to accommodate the 100-year design flood. It is recommended that the dam be classified as a significant hazard since there are camping areas downstream where a few lives could be lost in the event of a dam failure. No detrimental findings warranting further study were uncovered. Recommended remedial actions to be undertaken in the future include repair of the eroded areas and removal of the vegetation from the embankment, repointing of the masonry spillway and outfall headwall, inspection and repair of the drain's gate valve, and removal of silt from the sedimentation pond and connecting culverts.

  
\_\_\_\_\_  
Abraham Perera P.E.  
Project Manager

## TABLE OF CONTENTS

	<u>Page</u>
Assessment of General Conditions	
Overall View of Dam	
Table of Contents	
Preface	
Section 1 - Project Information	1-5
Section 2 - Engineering Data	6-7
Section 3 - Visual Inspection	8-9
Section 4 - Operational Procedures	10-11
Section 5 - Hydraulic/Hydrologic	12-13
Section 6 - Structural Stability	14-15
Section 7 - Assessments/Recommendations/ Remedial Actions	16-17

## FIGURES

Figure 1 - Regional Vicinity Map	
Figure 2 - Plan of Dam and Sedimentation Pond	
Figure 3 - Dam Section at 24" Diameter Drain and Principal Spillway	
Figure 4 - Section of Dike and Auxiliary Spillway	

## APPENDIX

Index List - Visual Inspection	i-ix
Index List - Engineering Data	x-xiii
Photographs	
Index List - Hydrologic and Hydraulic Data Computations	A1-A25

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines can be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of Phase I investigations is to identify expeditiously those dams that may pose hazards to human life or property. The assessment of the general condition of the dam is based on available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In the review of this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions will be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway test flood is based on the estimated "probable maximum flood" for the region (greatest reasonable possible storm runoff) or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM  
NAME OF DAM: LAKE OCCUITTUNK FED #NJ 00260

SECTION I - PROJECT INFORMATION

1.1 GENERAL

a. Authority

This report is authorized by the Dam Inspection Act, Public Law 92-367, and has been prepared in accordance with Contract FPM-36 between Louis Berger & Associates, Inc. and the State of New Jersey and its Department of Environmental Protection, Division of Water Resources. The state, in turn, is under agreement with the U.S. Army Engineer District, Philadelphia to have this inspection performed.

b. Purpose of Inspection

The purpose of this inspection is to evaluate the structural and hydraulic condition of the Lake Ocquittunk Dam and appurtenant structures and to determine if the dam constitutes a hazard to human life or property.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances

Lake Ocquittunk Dam is a 240-foot-long, 3-zone, earth structure with a drop inlet spillway at the right abutment. The embankment, which has a maximum height of 15.1 feet, is 20 feet wide at the crest with 2.5H:1V and 2H:1V slopes upstream and downstream respectively. The upstream portion of the embankment consists of compacted impervious fill. The center of the dam contains a 4-foot-wide impermeable clay core and cutoff trench. The downstream portion of the embankment is composed of ordinary bank run with rock fill at the toe of the slope. The masonry drop inlet structure has a 4 foot by 4 foot opening with flashboards and conducts flow to a 20-inch-diameter C.I. discharge pipe. The outlet headwall is masonry, and the trapezoidal channel is lined with riprap. A 24-inch diameter cast iron drain is located about

50 feet from the right abutment at invert elevation 95.5. The drain has concrete headwalls at both ends, a wheel-operated sluiceway at the entrance, and concrete anti-seep collars at each joint. Skellinger Road extends along the crest of the dam, providing paved protection in that area. The southeast end of Lake Ocquittunk is connected hydraulically to a sedimentation/stabilization pond by 3 pipe culverts under Skellinger Road. The pond is contained by a long, low earth dike whose crest elevation is 110. The dike is an integral hydraulic component of Lake Ocquittunk but has insufficient height or storage capacity to warrant a separate identification number. A 40-foot-wide concrete spillway near the north end of the dike has a crest elevation of 107, which is 0.08 feet higher than the spillway crest elevation at the Lake Ocquittunk Dam. Consequently, the pond and spillway serve to regulate the lake elevation and, in fact, act as a baffle to moderate rapid changes in water levels in Lake Ocquittunk. Inflow to the sedimentation pond (and subsequently Lake Ocquittunk) is augmented by diverting a portion of Big Flat Brook's flow through a concrete channel separation structure on a branch of that stream. The weir conducting flow to the pond is 10 feet long and has a crest elevation of 112.5. The weir returning flow to the channel is 37 feet long and has a crest elevation of 113, thus ensuring that the lake will also be fed even during low stream flow. At the same time, the greater length of the channel weir diverts excessive flows from the lake during periods of very high storm runoff.

b. Location

Lake Ocquittunk Dam, also known as Horseshoe Lake Dam, is situated on a tributary to Big Flat Brook. Skellinger Road extends along the crest of the dam, which is located approximately 700 feet east of the intersection of Skellinger and Flat Brook roads in Stokes State Forest, Sandyston Township, Sussex County, New Jersey.

c. Size Classification

The Lake Ocquittunk Dam has a maximum height of 15.1 feet and a maximum storage capacity of 80.5 acre-feet. Accordingly, this dam is in the small size category as defined by the criteria in the Recommended Guidelines for Safety Inspection of Dams (storage less than 1,000 acre-feet and height less than 40 feet).

d. Hazard Classification

The downstream channel between the dam and Big Flat Brook is undeveloped woodland. However there are several campsites located downstream near Big Flat Brook. Although they are located several feet above the river, it is possible that personal injury and the loss of a few lives could result from a dam failure. Accordingly, it is recommended that the dam be placed in the significant hazard category.

e. Ownership

The dam is owned by the State of New Jersey, Department of Environmental Protection, Bureau of Parks, Trenton, New Jersey.

f. Purpose of Dam

The dam was constructed for recreational purposes.

g. Design and Construction History

The dam was originally designed by the State Department of Conservation and Development, Division of Forests and Parks in 1933 and the plans were revised in 1938. Construction, which was performed by the Civilian Conservation Corps (CCC), began in 1938 and was completed in 1939.

h. Normal Operating Procedures

The dam is maintained and operated by personnel of the State Bureau of Parks. Maintenance crews are available all year for routine repairs and upkeep. The lake is normally lowered every winter for weed control. This winter (1980-1981) the lake was not drawn down due to the drought conditions that existed throughout much of the northern portion of the state. The dam is also monitored by state personnel in the course of their routine duties and during periods of abnormally heavy rainfall and runoff.

1.3 PERTINENT DATA

a. Drainage Area

Lake Ocquittunk Dam has a drainage area of 0.34 square miles that consists of an undeveloped, heavily forested mountainous region.

- b. Total spillway capacity (including culverts) at maximum pool elevation - 253 cfs
- c. Elevations (Assumed Datum)
- Top of dam - 110.6
  - Principal spillway crest - 106.92
  - Streambed at centerline of dam - 95.5
  - Auxiliary spillway crest - 107.0
- d. Reservoir
- Length of maximum pool (top of dam) - 1,015 feet
  - Length of recreation pool (principal spillway crest) - 960 feet
- e. Storage (acre-feet)
- Top of dam - 80.5
  - Recreation pool - 45.4
- f. Reservoir Surface (acres)
- Top of dam - 10.8
  - Recreation pool - 8.5
- g. Dam
- Type - Earth embankment with masonry drop inlet overflow near right abutment, low-level drain, and concrete auxiliary spillway on hydraulically connected sedimentation pond
  - Length - 240 feet
  - Height - 15.1 feet
  - Top width - 20.0 feet
  - Side slopes - 2.5H:1V upstream, 2H:1V downstream
  - Zoning - 3 zones: Fine, impervious compacted material in upstream embankment; impervious clay core; ordinary bank run in downstream embankment
  - Impervious blanket - None
  - Core - Impervious clay core 2 feet wide at crest and 4 feet wide at base of dam
  - Cutoff - 18 inch wide by 4 feet deep concrete cutoff wall contiguous with rock fill at toe of dam

Grout curtain - None

h. Diversion and Regulating Spillway

Type - Concrete weir at elevation 107 in sedimentation pond diverts high flows from Big Flat Brook before they enter Lake Ocquittunk

i. Spillway

Type - Principal - masonry drop inlet with 20-inch-diameter C.I. pipe outlet.

Auxiliary - concrete weir on sedimentation pond.

Weir length - Principal - variable: 4 feet to 7.5 feet  
Auxiliary - 40 feet

Gates - None

U/S channel - Lake or pond

D/S channel - Variably sloping, riprapped channel downstream of both spillways

j. Regulating Outlets

The low-level drain consists of a 24-inch-diameter cast iron pipe with 1 foot by 4 foot square concrete collars at each joint. Located near the center of the dam at invert elevation 95.5, the drain has reinforced concrete headwalls at both ends and a CALCO sluiceway at its upstream entrance.

## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN

Details of the initial design, hydraulic determinations, structural analyses, and subsurface information were available for review by the inspection team together with as-built plans and the various modifications undertaken since the initial construction. All design was performed by the State Department of Conservation and Development in conjunction with the CCC.

### 2.2 CONSTRUCTION

The original construction of Lake Ocquittunk Dam was performed by the CCC under the supervision of the State Division of Parks and Forests in 1938/39. Literature investigations indicate that the overburden on which the dam was constructed consists of some stratified glacial sediments, till, and recent alluvium. The depth of the core wall was determined by the subsurface conditions. Although not observed during the inspection, bedrock in this area is probably the Silurian High Falls Formation, which consists of alternating beds of hard red sandstone and shale.

### 2.3 OPERATIONS

General information pertaining to the operations at the dam were obtained from the Superintendent of Stokes State Forest, Department of Environmental Protection, Bureau of Parks, Box 260, Branchville, N.J. 07826. The dam is used for recreational purposes and partial drawdown is effected once a year for maintenance purposes.

### 2.4 EVALUATION

#### a. Availability

Sufficient engineering and construction data were available to evaluate the stability and hydraulic capacity of the dam and regulating pond.

#### b. Adequacy

The field inspection and review of the available design plans reveal that the dam is structurally sound and well built. It is believed that the data available are adequate to render this assessment.

and evaluate the hydraulic and hydrologic aspects of the dam within the purview of Public Law 92-367.

c. Validity

The validity of the engineering data available is not challenged and is accepted without recourse to further investigations.

## SECTION 3 - VISUAL INSPECTION

### 3.1 FINDINGS

#### a. General

Visual inspection of Lake Ocquittunk Dam took place on January 16 and February 5, 1981. Nothing could be seen in January as the dam was completely covered with snow and ice. By February, much of the snow had melted but the lake was still frozen. An ice jam on Big Flat Brook had diverted most of the stream's runoff to the secondary channel that eventually feeds the lake. About 2 feet of water was passing over the canal inlet weir, and a substantial discharge was noted at the auxiliary spillway located on the sedimentation pond. No discharge was observed at the principal spillway on Lake Ocquittunk Dam however, indicating that the hydraulic connection between the two bodies of water is constricted or frozen shut.

#### b. Dam

The embankment is a straight, relatively low structure lying between higher abutment zones. The road along the crest of the dam has recently been paved and appears to protect the crest from surface runoff and erosion. While the upstream face of the dam had a thick grass cover and one small tree growing on it, the downstream slope was completely overgrown with brush and trees up to 20 inches in diameter. A prior review of this dam by the inspection team revealed that a small wave-cut bench is present on the upstream face but the embankment has stabilized at the water line. Some seepage was noted near the outlet for the low-level drain; however, it appeared to be entering the channel from the direction of the spillway outlet. Since the spillway outlet is 8 feet higher in elevation than the low-level drain, it is likely that the seepage is moving laterally along the toe of the dam rather than through the dam. This assumption is supported by the fact that the dam has an impermeable clay core and cutoff that would severely curtail rapid ground water movement through the dam. Minor erosion was noted on the back slope at the sides of the drain outlet headwall. Although not part of this dam, conditions at the dike were observed. That structure was found to be completely overgrown, making it difficult to discern the outline of the structure.

c. Appurtenant Structures

While the principal outlet headwall is in good condition, the masonry inlet structure is severely weathered. Mortar is missing from between some of the joints and several blocks are missing. The steel trash grate is firmly affixed in place and appears to be functioning adequately. The wheel is missing from the gate stem to the 24-inch-diameter drain and the gangway from the dam to the gate column is also gone. The outlet pipe is partially silted in and a little rusty, while the concrete headwall exhibits minor spalling; however, both appear to be in good condition. The auxiliary spillway at the sedimentation pond also appeared in good condition, although the masonry sidewalls seem to need repointing. The separation wall at the channel separation structure appeared somewhat spalled on the top but otherwise in adequate condition.

d. Reservoir Area

The drainage area of this impoundment is a part of Stokes State Forest and, as such, is undeveloped and protected. The area surrounding the lake is forested and has moderate to steep slopes. According to park personnel, the sedimentation/stabilization pond is almost completely filled with sediment and, if not cleaned out, will soon block the hydraulic connection between the pond and the lake completely. The lake was completely frozen over at the time of the inspection, which prevented observing the problem firsthand. However, since this connection is essential to the proper regulation and protection of the dam, it is essential that the pond be cleaned out as soon as possible.

e. Downstream Channel

Both spillways discharge into masonry-lined trapezoidal channels only a short distance from Big Flat Brook. The area between the dam, dike, and Big Flat Brook is undeveloped and heavily wooded with clear, unobstructed channels to the stream.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES

Lake Ocquittunk Dam functions essentially unregulated throughout most of the year. Personnel of the State Bureau of Parks, who are responsible for the upkeep and maintenance of the dam, lower the lake every winter to help control weed growth in the lake and minimize ice damage to the dam and facilities at the lake. Park personnel also lower the water level during periods of heavy runoff and inflow to the lake.

### 4.2 MAINTENANCE OF DAM

The repair and maintenance of the dam is performed by personnel of the State Bureau of Parks. They are responsible for all facets of the dam's upkeep, including the drain and its controls, concrete and masonry repairs, sedimentation control, and landscaping. Park personnel indicate that, at present, the sedimentation pond is almost completely filled with silt. This condition should be corrected since it reduces the hydraulic capacity between the pond and Lake Ocquittunk and minimizes the effective flood storage capacity of the pond. The dam is routinely monitored by maintenance personnel and forest rangers, which facilitates corrective action when deficiencies are noted.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

The only regulating component at this dam is the 24-inch-diameter C.I. drain. As indicated above, park maintenance personnel are responsible for its maintenance. At the time of the inspection, the wheel was missing from the gate stem; presumably, the park personnel remove the wheel when it is not in use to prevent vandalism.

### 4.4 DESCRIPTION OF WARNING SYSTEM

The dam is monitored by state maintenance personnel and forest rangers in the course of their routine duties and during periods of abnormally heavy rainfall and runoff, at which time all dams in the State Forest are checked for possible problems. If a potentially hazardous condition is observed at Lake Ocquittunk Dam, the inspecting personnel are instructed to radio a report to headquarters and proceed to the downstream campgrounds to start evacuation procedures.

#### 4.5 EVALUATION

The operational and maintenance procedures in effect at this dam are felt to be adequate within the framework of its limited requirements. The emergency action plans and warning procedures in effect at this dam are considered adequate in view of the undeveloped nature of the downstream area.

## SECTION 5 - HYDRAULIC/HYDROLOGIC

### 5.1 EVALUATION OF FEATURES

#### a. Design Data

Pursuant to the Recommended Guidelines for Safety Inspection of Dams, Lake Ocquittunk Dam is a small size and significant hazard dam. Accordingly, the 100-year frequency storm was chosen as the design flood by the inspecting engineers. Inflow to the reservoir for the design storm was computed utilizing precipitation data from Technical Paper 40 and Technical Memorandum NWS Hydro-35 in conjunction with the HEC-1 DB computer program. The unit hydrograph was derived utilizing Snyder coefficients for the drainage area provided by the Corps of Engineers. Due to the unusual inflow conditions at the lake, runoff to the lake was calculated for the drainage area contributing directly to the lake combined with a portion of the runoff emanating from the Big Flat Brook drainage area upstream of Lake Ocquittunk. The portion of runoff entering the sedimentation pond was calculated to be 5.9% of the total Big Flat Brook runoff on the basis of the weir sizes of the flow separation structure at the inflow canal entrance. On the basis of these criteria, a peak inflow to the lake of 667 cfs was computed; when routed, this amount decreased to a maximum discharge of 251 cfs. Since the dam's combined spillway capacity is 253 cfs, the spillway can accommodate the 100-year flood and is adequate.

#### b. Experience Data

There are no streamflow records available for this site. The spillway appears to have functioned satisfactorily through the years, and according to park personnel, the dam has never been overtopped.

#### c. Visual Observation

During the inspection it was noted that the main channel of Big Flat Brook was blocked by a fallen tree and an ice jam that diverted most of the flow to the smaller secondary channel just upstream of the flow separation structure. This hydraulic component appeared to be functioning adequately as designed, and a substantial flow was entering the canal. Water was observed passing over the auxiliary spillway although not at the principal

spillway, suggesting that the hydraulic connection between the pond and the lake was obstructed since the auxiliary spillway weir is 0.08 foot higher in elevation than the principal spillway. The obstruction may be attributed to ice blockage since both lakes and the roadway culvert were completely frozen over. The park rangers were notified of the main channel obstruction following the inspection.

d. Overtopping Potential

Employing the discharge and spillway capacities contained herein, no overtopping would occur during a 100-year frequency storm. There are no records or indications that the dam has ever been overtopped, nor does there appear to be a significant potential for serious damage resulting from overtopping. The roadway pavement appeared to be in good condition and capable of withstanding moderate overtopping without causing erosion and affecting the dam.

e. Drawdown

The 24-inch-diameter C.I. outlet pipe is gate controlled and capable of drawing down the lake to elevation 95.5 in 17.9 hours.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### a. Visual Observations

No deficiencies of a structural nature were noted during the inspection of this dam. The horizontal alignment of the dam crest is good, and both upstream and downstream slopes are uniform and appear to be at true design grade. No indication of material movement such as settling, sloughing, or creeping was observed. Water was flowing uniformly over the entire auxiliary weir, indicating the symmetry and continuing stability of that structure.

#### b. Design and Construction Data

A review of the available design engineering data indicates that the design is well-engineered, reflecting a conservative approach and employing contemporary analytical techniques. Based on the present condition of the dam and a history of uninterrupted satisfactory performance since its construction, it is believed that additional studies or investigations relative to its stability are unnecessary at this time.

#### c. Operating Records

The performance of this structure has been satisfactory since its completion. However, there are no formal operating records available.

#### d. Post Construction Changes

There are no records of modifications at this dam, although a wooden walkway that extended from the embankment to the gate wheel is no longer in place. In addition, Skellinger Road, which extends along the crest of the dam, appears to be wider and slightly higher than indicated on the design drawings. The excellent condition of the road indicates that it has recently been repaved. With these exceptions, the dam and its auxiliary hydraulic components appear to be exactly as detailed in the design drawings.

#### e. Seismic Stability

Lake Ocquittunk Dam is located in Seismic Zone 1, in which seismic activity is slight and the

additional structural loading imparted thereby is generally insignificant. Experience indicates that earthen dams in Zone 1 that are stable under static loading conditions will maintain their structural integrity when subjected to the negligible dynamic loads imposed by the weak seismicity characteristic of this area. As indicated in the foregoing paragraphs, this dam appears to be stable in its present condition and configuration.

SECTION 7 - ASSESSMENTS/RECOMMENDATIONS/  
REMEDIAL ACTIONS

7.1 DAM ASSESSMENT

a. Safety

Subject to the inherent limitations of the Phase I visual inspection, Lake Ocquittunk Dam is judged to be in a good overall structural condition. The spillway capacity, including the culverts to the stabilization pond, is adequate to accommodate the 100-year frequency design flood. It is recommended that the dam be placed in the significant hazard category since the downstream area contains campgrounds that are utilized extensively for recreation during the spring and summer months.

b. Adequacy of Information

The design information made available by the NJDEP is deemed to be adequate regarding the analyses and evaluation of safe operation and structural stability.

c. Urgency

It is recommended that the remedial measures described in paragraph 7.2 be undertaken in the future, with the exception of cleaning out the pond, which should be undertaken as soon as possible.

d. Necessity for Further Study

In view of the overall condition of this dam, its hydraulic capacity, and the fact that it is continuously monitored and maintained by employees of the state, additional inspections or studies within the purview of Public Law 92-367 are deemed to be unnecessary.

7.2 RECOMMENDATIONS/REMEDIAL MEASURES

a. Recommendations


Under the present maintenance program, it is recommended that the following be performed in the future:

- Clear the brush and trees from the embankment and the upstream face of the dam as well as the dike.

- Fill, grade, and reseed the eroded area at the sides of the low level drain and repair the wave cut bench on the upstream face.
- Inspect and repoint the masonry sidewalls of the drop inlet spillway and channel where necessary.
- Remove the silt from the low-level drain outlet pipe.
- Inspect, repair, and test the valve for the drain.
- Monitor the seepage between the spillway and drain outlets.

b. O&M Procedures


The present maintenance program is considered satisfactory within the limits of the program. However, periodic inspection and repair, of the appurtenant structures described above should be included in the program when necessary. It is recommended that the blow-off valve be opened periodically to ensure its proper functioning and to keep the intake area free of excessive silting. The existing monitoring and emergency alert plan appears adequate in view of the undeveloped nature of the downstream area.



N.J 00260  
LAKE OCQUITTUNK DAM


Quad Sheet - Culvers Gap. N.J.-Penna.

FIGURE 1  
REGIONAL VICINITY MAP  
SCALE 1:24,000




PLAN OF LAKE OCQUITTUNK DAM  
 AND RELATED HYDRAULIC STRUCTURES

FIGURE 2




ELEVATIONS - LOW LEVEL DRAIN  
NOT TO SCALE




ELEVATIONS - PRINCIPAL SPILLWAY  
NOT TO SCALE

LAKE OCQUITTUNK  
MAIN DAM


FIGURE 3



AUXILIARY SPILLWAY SECTION  
NOT TO SCALE



TYPICAL CROSS SECTION OF DIKE  
NOT TO SCALE



ELEVATION  
INFLOW CANAL WEIR  
NOT TO SCALE

ELEVATION  
STREAM CHANNEL WEIR  
NOT TO SCALE

CHANNEL SEPARATION STRUCTURE

FIGURE 4

Check List  
Visual Inspection  
Phase 1

Name Dam Lake Ocquittunk Dam County Sussex State N.J. Coordinators NJDEP

Date(s) Inspection 1-16-81  
2-5-81 Weather cold and clear Temperature 20° F

Pool Elevation at Time of Inspection 100.9 A.D. Tailwater at Time of Inspection 95.5 A.D.

Inspection Personnel:

J. Ceravolo \_\_\_\_\_ T. Chapter \_\_\_\_\_

A. Perera \_\_\_\_\_

J. Greenstein \_\_\_\_\_

No representative of owner present.

\_\_\_\_\_  
T. Chapter Recorder

A.D. - Assumed Datum

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Light erosion next to outlet headwall. Wave cut bench at elevation of normal pool on upstream face.	Eroded areas should be filled. Upstream slope should be protected with riprap in wave action zone.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Both vertical and horizontal alignment is satisfactory. Dam crest paved with 20-foot-wide road.	Pavement protects crest from erosion. Could probably withstand good deal of overtopping with little damage to dam.
RIPRAP FAILURES	No riprap observed.	Riprap should be added to upstream face.

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
VEGETATION	Good grass cover and 1 tree on upstream slope. Downstream slope overgrown with brush and trees up to 20" in diameter. Dike overgrown with trees and brush.	All trees and brush should be removed. Difficult to see shape of dike.
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Embankment grades smoothly into both abutments.	
ANY NOTICEABLE SEEPAGE	Seepage to right of drain outlet. Probably comes from spillway outlet 8 feet higher and 35 feet to right of drain.	Dam has clay core and impervious embankment. Seepage appears to travel through stone fill along toe of dam.
STAFF GAGE AND RECORDER	None.	
DRAINS	Stone fill at toe of dam appears to function as drain although not described as such. Seepage through dam should be minimal based on composition.	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Not applicable. Cast iron pipe slightly rusty.	
INTAKE STRUCTURE	Light spalling on stem column.	Should be patched.
OUTLET STRUCTURE	Light efflorescence noted.	
OUTLET CHANNEL	Stone lined. No obstructions observed.	
EMERGENCY GATE	Wheel missing from gate stem. Appears to be operable since lake was much lower during inventory inspection in 1960.	

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	Auxiliary spillway on sedimentation pond in good condition. Sidewalls need repointing. Some stone missing.	Masonry should be replaced and repointed.
APPROACH CHANNEL	None	
DISCHARGE CHANNEL	Paved masonry apron and riprap channel clear and at true grade.	Several inches of flow discharging smoothly over weir and apron.
BRIDGE AND PIERS	None.	

PRINCIPAL GATED SILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE SILL	Masonry drop inlet in need of repointing. Some stone missing. Flashboards in place at time of inspection. Little or no flow.	Masonry should be replaced and repointed. Water should be flowing unless culvert between pond and lake is blocked.
APPROACH CHANNEL	None.	
DISCHARGE CHANNEL	Riprap-lined channel extends to drain outlet channel and Big Flat Brook. Appears clear.	
BRIDGE AND PIERS	None.	
GATES AND OPERATION EQUIPMENT	Flashboards in satisfactory condition.	

INSTRUMENTATION

VISUAL EXAMINATION MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
	None.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHER		vii

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Moderate to steep. Underdeveloped and heavily wooded. Lake and pond completely frozen. Combination of ice and sedimentation may be preventing flow between lake and sedimentation pond.	Culverts should be checked when ice thaws. Culverts should be cleared if blocked. Unable to observe conditions of culverts at present.
SEDIMENTATION	None observed but park personnel advise pond is almost completely filled with silt. This may be responsible for constriction at connecting culverts. More likely due to ice.	Sedimentation pond should be dredged back to original grades.

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Riprap-lined channels from both principal and auxiliary spillway appear clear to Big Flat Brook.	
SLOPES	Channel slopes moderate. Probably designed 2:1. Gradient conforms with terrain.	Channel lengths very short.
APPROXIMATE NO. OF HOMES AND POPULATION	None. Campground near Big Flat Brook about 1,200 feet downstream.	Appears to be above flood elevations.

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	Available. Microfilm - NJDEP, Prospect St., Trenton, N.J.
REGIONAL VICINITY MAP	Available. USGS Quad. Culvers Gap, N.J.-Penna.
CONSTRUCTION HISTORY	No details available.
TYPICAL SECTIONS OF DAM	Available - NJDEP
HYDROLOGIC/HYDRAULIC DATA	Design criteria available - NJDEP
OUTLETS - PLAN	Available - NJDEP
- DETAILS	Available - NJDEP
-CONSTRAINTS	Not Available
-DISCHARGE RATINGS	Not Available
RAINFALL/RESERVOIR RECORDS	Not Available

ITEM	REMARKS
SPILLWAY PLAN	Available - NJDEP
SECTIONS	Available - NJDEP
DETAILS	Available - NJDEP
OPERATING EQUIPMENT PLANS & DETAILS	Available - NJDEP Available - NJDEP

ITEM	REMARKS
------	---------

DESIGN REPORTS	Not Available.
----------------	----------------

GEOLOGY REPORTS	Not Available.
-----------------	----------------

DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Not Available. Not Available. Not Available.
---	--

MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	Not Available. Not Available. Not Available. Not Available.
---	--

POST-CONSTRUCTION SURVEYS OF DAM	Not Available.
----------------------------------	----------------

BORROW SOURCES.	Not Available.
-----------------	----------------

ITEM	REMARKS
------	---------

MONITORING SYSTEMS

None Observed.

MODIFICATIONS

None Noted.

HIGH FOOL RECORDS

Not Available.

POST CONSTRUCTION ENGINEERING  
STUDIES AND REPORTS

Not Available.

PRIOR ACCIDENTS OR FAILURE OF DAM  
DESCRIPTION  
REPORTS

Not Available.

MAINTENANCE  
OPERATION  
RECORDS

Not Available.



February, 1981

Channel Separation Structure



February, 1981

Influent Canal & Sedimentation Pond



February, 1981

Dike Crest and Auxiliary Spillway



February, 1981

Dam Crest and Gate Control Structure



February, 1981

Outlet for Principal Spillway



February, 1981

Outlet Structure 24"  $\emptyset$  C.I. Drain

CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 0.34 sq. m.

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 106.92 A.D.\* (45.4 acre-feet)

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): -

ELEVATION MAXIMUM DESIGN POOL: -

ELEVATION TOP DAM: 110.6 A.D.\* (80.5 acre-feet)

CRFST: Auxiliary spillway (on dike)

- a. Elevation 107
- b. Type Concrete weir w/sloping masonry apron
- c. Width 12"
- d. Length 40'
- e. Location Spillover At dike on sedimentation pond
- f. Number and Type of Gates None

OUTLET WORKS: Principal spillway (Main Dam)


- a. Type Masonry drop inlet with 20" C.I. pipe outlet
- b. Location Right abutment
- c. Entrance inverts 104
- d. Exit inverts 103.5
- e. Emergency draindown facilities 24" C.I. pipe drain at invert  
95.5

HYDROMETEOROLOGICAL GAGES: None

- a. Type \_\_\_\_\_
- b. Location \_\_\_\_\_
- c. Records \_\_\_\_\_

MAXIMUM NON-DAMAGING DISCHARGE: 253 cfs

\*A.D. - Assumed Datum



PLAN OF LAKE OCQUITTUNK DAM  
 AND RELATED HYDRAULIC STRUCTURES

BY J. [unclear] DATE 5/7/71  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
 SUBJECT \_\_\_\_\_

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. 42 OF 422  
 PROJECT [unclear]

Direct inflow from a [unclear] Area = 2.8 AC = .34 [unclear]

1. [unclear] [unclear] [unclear] [unclear]

a) Length of [unclear] [unclear] 1500'

$$\Delta H = 785' - 707' = 78' \quad V = \frac{78}{1250} = .062 = 6.2\%$$

$$V = 4.0 \text{ FPS}; \quad \text{Time} = \frac{1250}{4.0 \text{ FPS}} = .31 \text{ HRS}$$

c) [unclear] Flow [unclear] 3500

$$\Delta H = 1175 - 785 = 390' \quad S = 7.0$$

$$V = 2.1 \text{ FPS} \quad \frac{390}{1850}$$

$$\text{Time} = \frac{3500}{2.1 \text{ FPS}} = .49 \text{ HRS}$$

$$\Sigma t_c = .49 + .09 = .58 \text{ HRS}$$

c) overland flow path only  $\frac{\Delta e.l. - 1030 - 707}{L = 5300} = 6.1\%$   $V = 2.4 \text{ FPS}$   
 $T_c = \frac{1300}{2.4 \times 3600} = .74 \text{ hrs}$

2. California Culvert Method

a) Stream flow  $L = 1250' = .24 \text{ mi}$  ;  $H = 78'$

$$t_c = \left( \frac{11.9 \times L^3}{H} \right)^{.385} = \left[ \frac{11.9 \times (.24)^3}{78} \right]^{.385} = .09$$

b) overland flow = .49 hrs

$$\Sigma t_c = .49 + .09 = .58 \text{ HRS}$$

3. SCS METHODOLOGY using SCS TR-55  
 Soils Grain B

$$CN = 55$$

Y = Average Watershed slope = 6.5%

$$L = 1500 + 30 = 1530'$$

$$S = \frac{1000}{CN} - 10 = \frac{1818}{55} - 10 = 19.2 - 10 = 9.2$$

$$L = \text{LAG Time} = \frac{L^{.77} (S+1)^{.77}}{1900 Y^{.77}} = \frac{4500^{.77} (8.24)^{.77}}{1700 (6.5)^{.77}} = \frac{630 \times 4.52}{1900 \times 2.5}$$

$$L_0 \text{ Time} = .63 \text{ HRS}$$

$$t_c = L/.6 = 1.38 \text{ HRS}$$

$$\text{AVG } t_c = \frac{1.38 + .74 + .58}{3} = 0.90$$

$$\text{AVG LAG TIME} = T_c \times .6 = .54 \text{ HRS}$$

BY J.C. DATE 3/27/81  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
 SUBJECT \_\_\_\_\_

LOUIS BERGER & ASSOCIATES INC.

SHEET NO 15 OF 22  
 PROJECT CS 276

LAKE OCCUTTUNK DAM  
Test Storm: 100 Year Freq.  
FOR LAKE OCCUTTUNK AREA

Precipitation data from TP-40 & NOAA Technical  
 Memorandum NWS Hydro - 35

Time	Precip.	$\Delta$	RD	Time	Precip.	$\Delta$	RD
0.1	.91	.91	.03	3.1	4.30	.05	.91
0.2	1.46	.55	.03	3.2	4.34	.04	.35
0.3	1.81	.35	.03	3.3	4.38	.04	.23
0.4	2.07	.26	.03	3.4	4.41	.03	.17
0.5	2.30	.23	.02	3.5	4.43	.04	.12
0.6	2.46	.16	.03	3.6	4.48	.03	.10
0.7	2.63	.17	.02	3.7	4.52	.04	.09
0.8	2.77	.14	.04	3.8	4.56	.04	.08
0.9	2.89	.12	.03	3.9	4.60	.04	.07
1.0	3.00	.11	.03	4.0	4.63	.03	.06
1.1	3.10	.10	.03	4.1	4.66	.03	.06
1.2	3.20	.10	.04	4.2	4.69	.03	.05
1.3	3.29	.09	.03	4.3	4.72	.03	.05
1.4	3.36	.07	.03	4.4	4.75	.03	.05
1.5	3.44	.08	.04	4.5	4.78	.03	.04
1.6	3.51	.07	.04	4.6	4.82	.04	.05
1.7	3.58	.07	.05	4.7	4.85	.03	.04
1.8	3.65	.07	.05	4.8	4.87	.02	.04
1.9	3.71	.06	.05	4.9	4.90	.03	.04
2.0	3.76	.05	.05	5.0	4.93	.03	.04
2.1	3.82	.06	.05	5.1	4.96	.03	.03
2.2	3.87	.05	.07	5.2	4.98	.02	.03
2.3	3.92	.05	.07	5.3	5.01	.03	.03
2.4	3.97	.05	.07	5.4	5.04	.03	.03
2.5	4.02	.05	.10	5.5	5.06	.02	.03
2.6	4.07	.05	.11	5.6	5.09	.03	.03
2.7	4.12	.05	.14	5.7	5.12	.03	.03
2.8	4.17	.05	.16	5.8	5.15	.03	.02
2.9	4.21	.04	.26	5.9	5.17	.02	.03
3.0	4.25	.04	.55	6.0	5.20	.03	.02

BY J.S. DATE  
CHKD. BY DATE  
SUBJECT

LOUIS BERGER & ASSOCIATES INC.  
LAKE OCCUTTUNA  
FLAT BROOK FLOW

SHEET NO. A4 OF A23  
PROJECT C-116

### DRAINAGE AREA

- 1 TOTAL AREA WATERSHED 12.5 SQ. MILES INCLUDING WGS  
TOTAL AREA FLAT AREA AT LAKE BEING SPLIT  
INTO OCCUTTUNA CANAL 17.16 SAI.
- 2 NORTH AREA DRAINING DIRECTLY INTO LAKE OCCUTTUNA = 13.4 SAI
- 3 APPROXIMATE PERCENT OF DISCHARGE CONTRIBUTING INTO  
BRANCH FLOWING TO ENTRANCE CANAL TO OCCUTTUNA SEDIMENT  
POND AFTER SPLIT  
20' WIDTH BOTTOM OF BRANCH LEADING TO CANAL  
51' WIDTH BOTTOM OF MAIN STREAM

$$\% \text{ DISCHARGE FLOWING IN BRANCH} = \frac{20}{51+20} = 28\%$$

- ∴ EQUIVALENT AREA CONTRIBUTING TO CANAL FOR  
USE IN DRAWDOWN CALCULATIONS FOR LOW FLOW  
= .28 X 17.16 = 5.0 SAI

- 4 APPROXIMATE PERCENT OF TOTAL FLOWING TO  
ENTRANCE CANAL TO SEDIMENT POND.

PROPORTION OF WIDTHS OF CHANNELS:

$$\frac{\text{CANAL INTO POND}}{\text{CANAL + BRANCH FLAT AREA}} = \frac{10'}{10+37'} = .21 = 21\%$$

$$\% \text{ OF TOTAL FLOW OF FLAT BROOK FLOWING INTO OCCUTTUNA SEDIMENTATION POND} \\ = \frac{.28}{100} \times .21 = \underline{\underline{.059\%}}$$

BY J. Corvado DATE 3/27/01  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
 SUBJECT \_\_\_\_\_

LOUIS BERGER & ASSOCIATES INC.  
 OCQUITTUNA LAKE DAM  
 HYDROGRAPH OF FLAT FLOOD

SHEET NO. 15 OF 22  
 PROJECT CC 216

STATION 1 FLAT FLOOD  
 SYNTHETIC UNIT HYDROGRAPH

SNYDER COEFFICIENTS GIVEN BY CORP. OF ENGINEERS

$C_e = 2.0$   
 $C_p = .62$

$L = 50,000' = 9.47 \text{ miles}$   
 $L_{ca} = 28,500' = 5.4 \text{ miles}$

$T_p = \text{Lag Time} = C_e (L L_{ca})^{.3}$

$T_p = 2.0 (9.47 \times 5.4)^{.3}$

$T_p = 2.0 \times 3.26$

$T_p = \underline{6.51 \text{ Hours}}$

where  $C_e$  = C<sub>e</sub> representing  
 variation of watershed  
 slopes and storage  
 $C_p$  = peaky coefficient  
 $L$  = length of main stream  
 in miles  
 $L_{ca}$  = length along main  
 stream to a point  
 opposite watershed  
 centroid in miles  
 $T_p$  = Lag time in hrs.

When calculating portion of Flat Brook flow which  
 enters canal to OCQUITTUNA POND (NOT LAKE ITSELF  
 BUT SEDIMENTATION POND WITH ITS OWN SPILLWAY) USE  
 28% ratio of TOTAL FLAT BROOK DISCHARGE. THE  
 TAKE 21% of the 28% since the distance  
 further downstream is flow entering OCQUITTUNA

~~SEDIMENTATION POND~~  $(\frac{.21}{100} \times .28 \times .21 = .059 \text{ Ratio})$   
~~STABILIZING~~


BY J.C. DATE 1/21/71  
 CHKD. BY DATE  
 SUBJECT STAGE DISCHARGE OF SPILLWAY

LOUIS BERGER & ASSOCIATES INC.


SHEET NO. 46 OF 122  
 PROJECT NO. 275

QUANTITATIVE LAKE SEDIMENTATION

DATE PAID 11/20/70



ELEVATION VIEW



SIDE VIEW

A STAGE DISCHARGE OF SPILLWAY

WEIR FLOW: FROST HANDBOOK OF HYDRAULICS PG. 5-11 FIG. 5-2

L = 40' RECTANGULAR SHARP-CRESTED WEIR

1. FIND C FROM FIG. 5-2 (WEIR COEFFICIENT CURVE)

L = 420' DIKE OVERTOPPING FLOW C: FROST HANDBOOK

H/P VS. C CURVES

$$Q = C L H^{3/2}$$

ELEV.	SPILLWAY FLOW			DIKE OVERFLOW			TOTAL Q
	H	C	Q	H	C	Q	
107.0	0	-	0				0
107.5	.5	3.2	45				45
108.0	1	3.2	132				132
108.5	1.5	3.4	250				250
109.0	2	3.45	390				390
109.5	2.5	3.6	569				569
110.0	3	3.65	759				759
110.5	3.5	3.7	969	.5	2.6	386	1355
111.0	4.0	3.82	1222	1.0	2.7	1134	2356
111.5	4.5	3.85	1470	1.5	2.7	2053	3523



BY J.C. DATE  
 CHKD. BY DATE  
 SUBJECT

LOUIS BERGER & ASSOCIATES INC.



SHEET NO 118 OF 422  
 PROJECT 9-1/2

LAKES COUNTY, OHIO  
 STAGE DISCHARGE

FLOW INTO SEDIMENTATION POND  
 STAGE DISCHARGE OF COLLECT FROM LAKE SEQUITTUNIK  
 TO SEDIMENTATION POND

CONDITIONS

Water flows into pond from Lake Sequittunik  
 through a 3' diameter culvert. The culvert is  
 located on a road. The water level in the  
 pond is assumed to be 3' above the culvert  
 invert. The water level in the lake is assumed  
 to be 1.5' above the culvert invert. The  
 discharge is assumed to be 100 cfs.



A =  $7.07^2 \times 3 = 21.271$

Q = CA  $\sqrt{2.308} \sqrt{H}$   
 DISCHARGE - MAXIMUM AT H=10  
 PG. 4-35 7.50 4-11  
 L = 25' DIA = 3' CMP A = 7.07  
 C = 51

EL.	ΔH	C	Q (3'-36" CMP)	WATER DEPTH	PLUMBING POUNDS
107	0	.71	0		
108	1	.71	3.42	20	
109	1.5	.71	4.54	102	
110	2.4	.71	5.65	184	
111	3.5	.71	6.76	286	
107.5	.5	.71	3.25	85	
108.5	1.4	.71	4.47	143	
110.6	3.6	.71	6.76	216	


$111.5^2 \times 3.5 \times 2.308 \times 51 = 2164$

BY J.C. DATE 3/27/81  
CHKD. BY DATE  
SUBJECT

LOUIS BERGER & ASSOCIATES INC.  
LAKE OCCUTTUNK DAM  
STAGE DISCHARGE

SHEET NO 49 OF 122  
PROJECT 9-276

FIND GOVERNING CONDITION OF FLOW: PIPE FLOW OR WEIR FLOW





BY J.C. DATE 3/27/81  
 CHKD BY DATE  
 SUBJECT

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. A10 OF A22  
 PROJECT

LAKELAND OCCUPATIONAL DAM  
 STAGE DISCHARGE (CONT'D.)

1. PIPE FLOW (CULVERT)		2. INLET FLOW (WEIR)		3. FLOW OVER DAM		4. FLOW INTO SEEDING POND		TOTAL Q
EL.	ΔH	C	H	Q	H OVER BACK WEIR	Q	ΔH	Q
106.92	2.52	84	-	-				0
107.0	2.6	"	0.8	3.2	4	10		10
107.5	3.1	"	1.5	3.2	4	6		6
108.0	3.6	"	1.0	3.0	4.9	10		10
108.5	4.1	"	1.5	3.4	5.15	55		55
109.0	4.6	"	2.0	3.45	6.2	66		66
109.5	5.1	"	2.5	3.6	7.05	105		105
110.0	5.6	"	3.0	3.65	7.5	148		148
110.5	6.1	"	3.5	3.7	7.5	158		158
110.6	6.2	"	3.6	3.7	7.5	176		176
111.0	6.6	"	4.0	3.8	7.5	235		235
111.5	7.1	"	4.5	3.9	7.5	287		287




Q = CA V2/3 ΔH  
 A = 2.19 ft<sup>2</sup>  
 SOURCE: HANDBOOK OF HYDRAULIC TABLE 4-11 P 4-37 FOR C  
 ΔH = el WE - WS el OUT - 11.44

\* CIP TO 10 - 20 FT. OF SLOPING SIDE  
 IN TABLE AS 1/2 THE LENGTH.

0	95	133	173	194	221	253	428	818
---	----	-----	-----	-----	-----	-----	-----	-----

# OCQUITTUNK DAM STAGE-DISCHARGE CURVE




BY J.S. DATE 7/77  
 CHKD. BY DATE  
 SUBJECT

LOUIS BERGER & ASSOCIATES INC.  
 ACQUISITION, LAND  
 STORAGE

DATE NO. 4/12 OF 22  
 PROJECT C-76

AREA LAND AT ELE. 108.72 = 8.5 AC. MEAN SURFACE  
 AREA LAND AT CLEV. 110.0 = 10.6 AC. " " " " " "  
 AREA LAND AT CLEV. 120.5 = 17 AC. MEAN SURFACE

$$\Delta \text{ STORAGE} = Y(X + \Delta X)$$



BETWEEN 108.72 & 110

$$\frac{10.6 - 8.5}{3.28} = \frac{2.1}{3.28} = .7 \text{ AC/FT}$$

$$\Delta Y = .7/2 = .35 \text{ AC}$$

BETWEEN 110 & 120

$$\frac{17 - 10.6}{10} = \frac{6.4}{10} = .64 \text{ AC/FT}$$

$$\Delta Y = .64/2 = .32 \text{ AC}$$

ELEV.	HT. ABOVE SPILLWAY (FT.)	(Y + ΔY) AC.	SURFACE AREA (AC)	UNDERPASS STORAGE (AC FT.)	TOTAL SURFACE STORAGE (AC-FT.)	TOTAL STORAGE (AC-FT.)
95.5			0			
120			2.72			6.12
107	.08		8.5	0.7 NEGLIG.	0.7 NEGLIG.	45.39
108	1	8.85	9.2	8.85	8.85	54.24
109	2	9.2	9.9	18.4	18.4	63.79
110	3	9.55	10.6	28.65	28.65	74.05
110.6	3.6 (.6)	10.79		6.45	35.10	80.50

\* Approximate, subject to final survey

BY J.C. DATE 7/1/61  
CHKD. BY DATE  
SUBJECT

LOUIS BERGER & ASSOCIATES INC.

LAKE OQUITTUNK

DRAWDOWN TIME OF LAKE

SHEET NO 413 OF 422  
PROJECT C-76

1. DRAWDOWN OUT OF MAIN LAKE BY 24" CMP  
NORMAL POOL ELEV. = 106.92 SAY 107 M.L.  
INLET & EXIT ELEVATION = 95.50  
VOLUME OF STORAGE MEASURED FROM EXIST. DRAWING CONTAINS  
45.4 AC.FT.

2. DRAWDOWN OUT OF ENTRANCE POND  
NORMAL POOL ELEV. = 107  
EL CURV UNDER RD. = 102.5  
VOLUME STORAGE MEASURED FROM EXIST. DRAWING CONTAINS  
AREA @  $\leq 107$  = .93 AC  
AREA @  $\leq 102.5$  = 0  
VOLUME = 1.87 AC.FT.

TOTAL VOLUME = 45.4 + 1.87 = 47.27 AC.FT.

3. INFLOW FROM DRAINAGE AREA  
ASSUME 1 cfs/acre.  
FROM PAGE A4:  
TOTAL AREA CONTRIB. INTO LAKE OQUITTUNK = 5.085 ac + .345 ac  
= 5.43 ac for 1 cfs/acre

∴ INFLOW = 5.43 cfs

4. DRAWDOWN FLOW OUT OF LAKE  
EL. 110.6

▽ WS EL. 107 M CREST OF POOL

1 24" CMP L=74'  $\Delta H = 36.5$

$$Q = CA \sqrt{2g \Delta H} \quad A_{24"} = 3.14 \text{ ft}^2$$

FIND C FROM APPROX. OF HYDRAULIC, HANDB. TABLE 4-11 P. 4-37 (C = CMP COEFF.)

BY J.C. DATE 3/27/11  
 CHKD. BY DATE  
 SUBJECT

LOUIS BERGER & ASSOCIATES INC.

SHEET NO A14 OF A22  
 PROJECT S-07

LAKE ...  
 DRAWDOWN TIME (CONT'D)

$C = .73$   $\Delta H$  FROM CREST POOL TO  $\Phi$  PIPE = 10.5'  
 DRAWDOWN BETWEEN EL 107 & 97.5 TOP OF PIPE

$MAX Q = .73 \times 3.14 \sqrt{29(10.5)} = 59.6 cfs$  AT 107'

5

DRAWDOWN TIME

EL.	STORAGE AC. FT.	FLOW cfs	AVG FLOW cfs	INFLOW	AVG. FLOW OUT	TIME
107	39.7	59.6	47 cfs	- 5.42	= 41.58	1.6 HRS
100		34.4				
95.5	6.1	0	17.2	- 5.42	= 11.73	6.3 HRS
TOTAL TIME						<u>17.9 HOURS</u>

$\frac{39.7 \times 43560}{41.58 \times 3600} + \frac{6.1 \times 43560}{11.73 \times 3600} = 17.9 \text{ HRS}$

BY J.C. DATE 7/2/81  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
 SUBJECT \_\_\_\_\_

**LOUIS BERGER & ASSOCIATES INC.**

SHEET NO 415 OF A22  
 PROJECT LAKE DCQUITTONE RIVER

A1	LAKE DCQUITTONE									
A2	J. CERAVOLD									
A3	MARCH 10, 1981									
B	100	0	6	0	0	0	0	0	0	0
B1	3									
K	0	1								
K1	INFLOW HYDROGRAPH TO RESERVOIR									
M	0	2	34							
Q	60									
Q1	.03	.03	.03	.03	.02	.03	.02	.04	.03	.03
Q1	.03	.04	.03	.03	.04	.04	.05	.06	.07	.06
Q1	.05	.07	.07	.07	.10	.11	.11	.11	.11	.11
Q1	.01	.05	.05	.05	.12	.12	.12	.12	.12	.12
Q1	.05	.05	.05	.05	.04	.04	.04	.04	.04	.04
Q1	.03	.03	.03	.03	.03	.03	.03	.03	.03	.03
T										
W2		.570								
X	0	0	1							
K	1	2								
K1	ROUTED FLOWS THROUGH RESERVOIR									
Y				1	1					
Y1	1									-1
Y4	106.9	107.5	108.5	109	110	110.6	111			
Y5	0	91	173	194	221	253	428			
4A	8.5	10.6	17							
4E	106.9	110	170							
4F	106.9									
4D	110.5									
K	99									

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS  
 RUNOFF HYDROGRAPH AT 1  
 ROUTE HYDROGRAPH TO 2  
 END OF NETWORK

JOB SPECIFICATION

NG	NHR	NMIN	IDAY	IRF	IMID	METRC	IPLT	IPRT	NSTAG
100	0	6	0	0	0	0	0	0	0
			JOPEN	NWT	LROPT	TRACE			
			3	0	0	0			

INFLOW HYDROGRAPH TO RESERVOIR

ISTAG	ICOMP	IECON	ITAPE	UNIT	IPRT	INAME	INSTAG	INLTC
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

IHYDG	IUHG	TAREA	SNAP	FRSBA	FRPC	RATIO	INFLW	ICOME	LOCAL
0	2	0.34	0.00	0.00	0.00	0.000	0	0	0
PROFIT PATTERN									
0.03	0.03	0.03	0.03	0.02	0.03	0.02	0.04	0.03	0.03
0.03	0.04	0.03	0.03	0.04	0.04	0.05	0.05	0.05	0.05
0.05	0.07	0.07	0.07	0.10	0.11	0.11	0.11	0.11	0.11
0.01	0.05	0.05	0.05	0.12	0.12	0.12	0.12	0.12	0.12
0.06	0.05	0.05	0.05	0.04	0.05	0.04	0.04	0.04	0.04
0.03	0.03	0.03	0.03	0.03	0.03	0.03	0.03	0.03	0.03

LOSS DATA

LROPT	STRKR	DLTKR	RTIOL	ERAIN	STRAS	RTIOW	STRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	0.50	0.10	0.00	0.00

UNIT HYDROGRAPH DATA

BY J.C. DATE 7/2/61  
 CHKD. BY DATE  
 SUBJECT

LOUIS BERGER & ASSOCIATES INC.

LAKE SUPERIOR DAM  
 FOOT OF THE LAKE DAM

SHEET NO. A16 OF A22  
 PROJECT NO. 70

SUB-AREA RUNOFF COMPUTATION

PRECIP DATA  
 NP STORM DAI DAK  
 50 0.00 0.00 0.00  
 TC= 0.00 LAG= 0.57

RECESSION DATA  
 STRTG= 0.00 GRCSN= 0.00 RTDR= 1.00

UNIT HYDROGRAPH 30 END OF PERIOD ORDINATES, TC= 0.00 HOURS, LAG= 0.57 VOL= 1.00

19.	57.	118	174	247.	264.	258	230.	180	145
108	83	65	50	38.	29	23	17.	13	10
8	6	5.	4.	3	2.	2	1.	1.	0

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

\*\*\*\*\*

HYDROGRAPH ROUTING

NSTPS NSTDL LAG AMSKA X TSK STORA ISPRAT  
 1 0 0 0.000 0.000 0.000 0 -

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

\*\*\*\*\*

PEAK 6-HOUR 24-HOUR 72-HOUR AREA

BY J.C. DATE 7/2/81  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
 SUBJECT \_\_\_\_\_

**LOUIS BERGER & ASSOCIATES INC.**  
 LAKE ERQUITTONT DAM  
 HEC-1 DT. FOR LAKE AREA

SHEET NO A-17 OF A-22  
 PROJECT CS-276

MO	DA	HR	MIN	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW COMP Q	FLOW	DA	HR	MIN	PERIOD	RAIN	EXCS	LOSS	COMP Q	
1	01	0	06	1	0.03	0.00	0.03	0	1.01	1	01	5	06	51	0.03	0.01	0.01	107
1	01	0	13	2	0.03	0.00	0.03	0	1.01	1	01	5	13	52	0.03	0.01	0.01	93
1	01	0	20	3	0.03	0.00	0.03	0	1.01	1	01	5	20	53	0.03	0.01	0.01	69
1	01	0	27	4	0.03	0.00	0.03	0	1.01	1	01	5	27	54	0.03	0.01	0.01	82
1	01	0	34	5	0.02	0.00	0.02	0	1.01	1	01	5	34	55	0.03	0.01	0.01	75
1	01	0	41	6	0.03	0.00	0.03	0	1.01	1	01	5	35	56	0.03	0.01	0.01	63
1	01	0	48	7	0.02	0.00	0.02	0	1.01	1	01	5	42	57	0.03	0.01	0.01	63
1	01	0	55	8	0.04	0.00	0.04	0	1.01	1	01	5	48	58	0.01	0.01	0.01	58
1	01	0	02	9	0.03	0.00	0.03	0	1.01	1	01	5	54	59	0.03	0.01	0.01	57
1	01	1	00	10	0.03	0.00	0.03	0	1.01	1	01	6	00	60	0.02	0.01	0.01	50
1	01	1	07	11	0.03	0.00	0.03	0	1.01	1	01	6	06	61	0.00	0.00	0.00	47
1	01	1	14	12	0.04	0.00	0.04	0	1.01	1	01	6	12	62	0.00	0.00	0.00	43
1	01	1	21	13	0.03	0.00	0.03	0	1.01	1	01	6	18	63	0.00	0.00	0.00	39
1	01	1	28	14	0.03	0.00	0.03	0	1.01	1	01	6	24	64	0.00	0.00	0.00	33
1	01	1	35	15	0.04	0.00	0.04	0	1.01	1	01	6	30	65	0.00	0.00	0.00	28
1	01	1	42	16	0.04	0.00	0.04	0	1.01	1	01	6	36	66	0.00	0.00	0.00	23
1	01	1	49	17	0.05	0.01	0.01	1	1.01	1	01	6	42	67	0.00	0.00	0.00	18
1	01	1	56	18	0.05	0.04	0.01	3	1.01	1	01	6	48	68	0.00	0.00	0.00	14
1	01	2	03	19	0.05	0.04	0.01	B	1.01	1	01	6	54	69	0.00	0.00	0.00	11
1	01	2	10	20	0.05	0.04	0.01	15	1.01	1	01	7	00	70	0.00	0.00	0.00	8
1	01	2	17	21	0.05	0.04	0.01	35	1.01	1	01	7	06	71	0.00	0.00	0.00	5
1	01	2	24	22	0.07	0.06	0.01	36	1.01	1	01	7	12	72	0.00	0.00	0.00	4
1	01	2	31	23	0.07	0.06	0.01	49	1.01	1	01	7	18	73	0.00	0.00	0.00	3
1	01	2	38	24	0.07	0.06	0.01	57	1.01	1	01	7	24	74	0.00	0.00	0.00	2
1	01	2	45	25	0.10	0.09	0.01	72	1.01	1	01	7	30	75	0.00	0.00	0.00	1
1	01	2	52	26	0.11	0.10	0.01	81	1.01	1	01	7	36	76	0.00	0.00	0.00	1
1	01	3	00	27	0.14	0.13	0.01	89	1.01	1	01	7	42	77	0.00	0.00	0.00	1
1	01	3	07	28	0.16	0.15	0.01	99	1.01	1	01	7	48	78	0.00	0.00	0.00	1
1	01	3	14	29	0.25	0.25	0.01	116	1.01	1	01	8	00	79	0.00	0.00	0.00	1
1	01	3	21	30	0.25	0.25	0.01	139	1.01	1	01	8	06	80	0.00	0.00	0.00	1
1	01	3	28	31	0.25	0.25	0.01	175	1.01	1	01	8	12	81	0.00	0.00	0.00	1
1	01	3	35	32	0.25	0.25	0.01	235	1.01	1	01	8	18	82	0.00	0.00	0.00	1
1	01	3	42	33	0.25	0.25	0.01	326	1.01	1	01	8	24	83	0.00	0.00	0.00	1
1	01	3	49	34	0.17	0.17	0.01	431	1.01	1	01	8	30	84	0.00	0.00	0.00	1
1	01	3	56	35	0.12	0.11	0.01	433	1.01	1	01	8	36	85	0.00	0.00	0.00	1
1	01	4	03	36	0.09	0.09	0.01	457	1.01	1	01	8	42	86	0.00	0.00	0.00	1
1	01	4	10	37	0.09	0.08	0.01	459	1.01	1	01	8	48	87	0.00	0.00	0.00	1
1	01	4	17	38	0.06	0.07	0.01	416	1.01	1	01	8	54	88	0.00	0.00	0.00	1
1	01	4	24	39	0.07	0.06	0.01	350	1.01	1	01	9	00	89	0.00	0.00	0.00	1
1	01	4	31	40	0.06	0.05	0.01	403	1.01	1	01	9	06	90	0.00	0.00	0.00	1
1	01	4	38	41	0.06	0.05	0.01	404	1.01	1	01	9	12	91	0.00	0.00	0.00	1
1	01	4	45	42	0.05	0.04	0.01	297	1.01	1	01	9	18	92	0.00	0.00	0.00	1
1	01	4	52	43	0.05	0.04	0.01	297	1.01	1	01	9	24	93	0.00	0.00	0.00	1
1	01	4	59	44	0.05	0.04	0.01	235	1.01	1	01	9	30	94	0.00	0.00	0.00	1
1	01	5	06	45	0.04	0.03	0.01	230	1.01	1	01	9	36	95	0.00	0.00	0.00	1
1	01	5	13	46	0.03	0.03	0.01	192	1.01	1	01	9	42	96	0.00	0.00	0.00	1
1	01	5	20	47	0.03	0.03	0.01	153	1.01	1	01	9	48	97	0.00	0.00	0.00	1
1	01	5	27	48	0.04	0.03	0.01	148	1.01	1	01	9	54	98	0.00	0.00	0.00	1
1	01	5	34	49	0.04	0.03	0.01	132	1.01	1	01	9	00	99	0.00	0.00	0.00	1
1	01	5	41	50	0.03	0.03	0.01	118	1.01	1	01	10	06	100	0.00	0.00	0.00	1
SUM 5.20 4.25 0.94 4343 264.56																		
( 137 ) ( 108 ) ( 24 ) ( 1 )																		
9342																		
255																		
4.26																		
108.20																		
77																		
95																		

CFE 156. 93 53  
 CMG 4 3  
 INCHES 4 26 4 26  
 MM 108.15 108.20 108.20  
 AC-FT 77 77  
 THOUS CU M 95 95

BY J.C. DATE 7/1/77  
 CHKD BY DATE 7/1/77  
 SUBJECT

**LOUIS BERGER & ASSOCIATES INC.**  
 1000 ...  
 ACCIDENT ...

SHEET NO. 415 OF A2  
 PROJECT NO. 276

**ROUTED FLOWS THROUGH RESERVOIR**

	ISTAG 2	ICOMP 1	ICONN 0	ITRPF 1	ICUT 0	ISRT 0	ISUP 1	ISTAG 0	IAUTG 0
	GROSS		AVG		REL		L276		
	0 0	0 000	0 00	1	0	0	0	0	
STAGE	106.90	107.50	108.50	109.50	110.00	110.60	111.00		
FLOW	0 00	91 00	173 00	194 00	201 00	251 00	478 00		
SURFACE AREA=	9.	11.	17						
CAPACITY=	0	30	162						
ELEVATION=	107	110	120						
	CREL	SPWID	CCON	EXPW	ELEVEL	CGQL	CAREA	EXPL	
	108.9	0 0	0 0	0 0	0 0	0 0	0 0	0 0	

**DAM DATA**

TOPEL	CGOD	EXPD	DAMWID
110.6	0 0	0 0	0

**END-OF-PERIOD HYDROGRAPH ORDINATES**

MD	DA	HR	MIN	PERIOD	HOURS	INFLOW	OUTFLOW	STORAGE	STAGE
1	01	0	00	1	0 10	0	0	0	106.9
1	01	0	12	2	0 20	0	0	0	106.9
1	01	0	18	3	0 30	0	0	0	106.9
1	01	0	24	4	0 40	0	0	0	106.9
1	01	0	30	5	0 50	0	0	0	106.9
1	01	0	36	6	0 59	0	0	0	106.9
1	01	0	42	7	1 08	0	0	0	106.9
1	01	0	48	8	1 17	0	0	0	106.9
1	01	0	54	9	1 26	0	0	0	106.9
1	01	1	00	10	1 35	0	0	0	106.9
1	01	1	06	11	1 44	0	0	0	106.9
1	01	1	12	12	1 53	0	0	0	106.9
1	01	1	18	13	2 02	0	0	0	106.9
1	01	1	24	14	2 11	0	0	0	106.9
1	01	1	30	15	2 20	0	0	0	106.9
1	01	1	36	16	2 29	0	0	0	106.9
1	01	1	42	17	2 38	1	0	0	106.9
1	01	1	48	18	2 47	3	0	0	106.9
1	01	1	54	19	2 56	6	1	0	106.9
1	01	2	00	20	3 05	12	2	0	106.9
1	01	2	06	21	3 14	20	5	0	106.9
1	01	2	12	22	3 23	36	8	0	107.0
1	01	2	18	23	3 32	46	13	1	107.0
1	01	2	24	24	3 41	59	19	1	107.0
1	01	2	30	25	3 50	71	25	1	107.1
1	01	2	36	26	3 59	84	32	2	107.1
1	01	2	42	27	4 08	98	40	2	107.2
1	01	2	48	28	4 17	116	49	3	107.2
1	01	2	54	29	4 26	137	60	3	107.3
1	01	3	00	30	4 35	175	73	4	107.4
1	01	3	06	31	4 44	206	90	5	107.5
1	01	3	12	32	4 53	266	104	7	107.7
1	01	3	18	33	5 02	350	124	9	107.9
1	01	3	24	34	5 11	452	151	12	108.2
1	01	3	30	35	5 20	573	177	15	108.6
1	01	3	36	36	5 29	727	194	19	109.0
1	01	3	42	37	5 38	914	204	23	109.4
1	01	3	48	38	5 47	1116	213	27	109.7
1	01	3	54	39	5 56	1330	231	33	110.0
1	01	4	00	40	6 05	1557	244	39	110.2
1	01	4	06	41	6 14	1804	251	34	110.4
1	01	4	12	42	6 23	2071	247	30	110.5
1	01	4	18	43	6 32	2357	250	35	110.5
1	01	4	24	44	6 41	2654	251	26	110.6
1	01	4	30	45	6 50	2952	250	33	110.6
1	01	4	36	46	6 59	3250	246	35	110.5
1	01	4	42	47	7 08	3548	237	30	110.5
1	01	4	48	48	7 17	3846	221	24	110.4
1	01	4	54	49	7 26	4144	208	17	110.3
1	01	5	00	50	7 35	4442	194	12	110.2
1	01	5	06	51	7 44	4740	177	9	110.1
1	01	5	12	52	7 53	5038	157	6	110.0

BY DL DATE 7/7/70  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
 SUBJECT \_\_\_\_\_

**LOUIS BERGER & ASSOCIATES INC.**

*DAM CONDITIONS DAM  
 PROFILE FOR LINE AREA*

SHEET NO. 117 OF 122  
 PROJECT 5-1-70

1.01	5.18	53	5.50	89	209	29	107.9
1.01	5.24	54	5.50	82	217	26	107.8
1.01	5.30	55	5.50	75	214	27	107.7
1.01	5.36	56	5.50	68	211	26	107.6
1.01	5.42	57	5.70	63	208	24	107.5
1.01	5.48	58	5.80	56	205	23	107.4
1.01	5.54	59	5.90	54	201	22	107.3
1.01	5.60	60	6.00	50	198	21	107.2
1.01	6.06	61	6.10	47	195	20	107.0
1.01	6.12	62	6.20	45	190	18	106.9
1.01	6.18	63	6.30	39	185	17	106.8
1.01	6.24	64	6.40	35	180	16	106.7
1.01	6.30	65	6.50	28	174	15	106.5
1.01	6.36	66	6.60	23	165	14	106.4
1.01	6.42	67	6.70	16	155	12	106.3
1.01	6.48	68	6.80	14	148	11	106.2
1.01	6.54	69	6.90	11	137	10	106.1
1.01	7.00	70	7.00	8	127	9	107.9
1.01	7.06	71	7.10	5	119	8	107.8
1.01	7.12	72	7.20	5	110	7	107.7
1.01	7.18	73	7.30	4	103	6	107.5
1.01	7.24	74	7.40	3	95	6	107.6
1.01	7.30	75	7.50	2	87	5	107.5
1.01	7.36	76	7.60	2	77	4	107.4
1.01	7.42	77	7.70	1	68	4	107.3
1.01	7.48	78	7.80	1	57	3	107.3
1.01	7.54	79	7.90	1	45	3	107.2
1.01	8.00	80	8.00	1	45	2	107.2
1.01	8.06	81	8.10	0	37	2	107.1
1.01	8.12	82	8.20	0	27	0	107.1
1.01	8.18	83	8.30	0	24	0	107.1
1.01	8.24	84	8.40	0	24	1	107.1
1.01	8.30	85	8.50	0	21	1	107.0
1.01	8.36	86	8.60	0	18	1	107.0
1.01	8.42	87	8.70	0	15	1	107.0
1.01	8.48	88	8.80	0	12	1	107.0
1.01	8.54	89	8.90	0	10	1	107.0
1.01	9.00	90	9.00	0	10	1	107.0
1.01	9.06	91	9.10	0	9	0	107.0
1.01	9.12	92	9.20	0	7	0	106.9
1.01	9.18	93	9.30	0	6	0	106.9
1.01	9.24	94	9.40	0	6	0	106.9
1.01	9.30	95	9.50	0	5	0	106.9
1.01	9.36	96	9.60	0	4	0	106.9
1.01	9.42	97	9.70	0	4	0	106.9
1.01	9.48	98	9.80	0	3	0	106.9
1.01	9.54	99	9.90	0	3	0	106.9
1.01	10.00	100	10.00	0	2	0	106.9

PEAK OUTFLOW IS 251. AT TIME 4.40 HOURS

CFS	251.	152	93.	93.	9329
CMS	7.	4	3	3	264
INCHES		4.17	4.25	4.25	4.25
NM		105.67	108.05	108.05	108.05
AC-FT		74	77	77	77
THOUS CU M		93.	95	95	95

**RUNOFF SUMMARY, AVERAGE FLOW IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)**

		AREA IN SQUARE MILES (SQUARE KILOMETERS)				
HYDROGRAPH AT	1	667.	156	93	93	0.34
		( 18.88 )	( 4.41 )	( 2.65 )	( 2.65 )	( 0.88 )
ROUTED TO	2	251.	152	93	93	0.34
		( 7.10 )	( 4.31 )	( 2.64 )	( 2.64 )	( 0.88 )

**SUMMARY OF DAM SAFETY ANALYSIS**

	ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM			
	ST. RAGL	106.90	106.90	110.60			
	OUTFLOW	0.	0	253			
RATIO OF P.M.F. TO C.C.	MAXIMUM RESERVOIR W.S. TO Z	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW TO C.C.	TIME OF FAILURE HOURS
0.00	110.52	0.00	36	251	0.00	4.40	0.00

BY J.C. DATE 7/2/71  
 CHKD. BY DATE  
 SUBJECT H.S. 100 FLAT BROOK

LOUIS BERGER & ASSOCIATES INC.

SHEET NO. 1 OF 2  
 PROJECT

A1	LAKE HEBBET FLAT BROOK									
A2	CONVEYING									
A3	MARCH 10, 1961									
R	200	0	15	0	0	0	0	0	0	0
L1	5									
J	1	1	1							
J1	059									
K	0	3								
K1	INFLOW HYD FROM FLAT BROOK									
M	0	1	18.5		18.5					
O	24									
O1	05	07	07	08	09	10	11	13	15	19
O1	30	64	1.66	40	25	14	14	12	10	09
O1	03	08	07	06						
T							5	1		
W	6.51	62								
X	0	0	1							
W	1	4								
K1	ROUTED FLOW THROUGH ENTRANCE POND									
Y			1	1						
Y1	1							-1		
Y4	707	707.5	708	708.5	709	709.5	710	710.5	711	
Y5	0	45	132	250	385	529	759	1255	2055	
Y6	1	1.5								
Y7	707	712								
Y8	707									
Y9	710									
Y	95									

JOB SPECIFIC DATA										
UB	NBR	NMIN	UBAY	UBR	UBRM	UBRZ	UBR1	UBR2	UBR3	UBR4
200	0	15		0	0	0	0	0	0	0
JOB SPECIFIC DATA										
	UBR5	UBR6	UBR7	UBR8	UBR9	UBR10	UBR11	UBR12	UBR13	UBR14
	5	0	0	0	0	0	0	0	0	0

INFLOW HYD FROM FLAT BROOK										
	ISTAG	ICOMP	IFLOW	IFRST	IFL2	IFL3	IFL4	IFL5	IFL6	IFL7
	0	0	0	0	0	0	0	0	0	0

HYDROGRAPH DATA										
	THYD5	ILHC	TAREA	CMAX	THYD6	THYD7	RATIO	LENGTH	ISAG	ICORR
	0	1	18.50	0.00	18.50	0.00	0.000	0	0	0
SPECIFIC PATTERNS										
0.05	0.07	0.07	0.00	0.07	0.10	0.11	0.13	0.15	0.1	0.1
0.10	0.14	1.66	0.40	0.25	0.16	0.14	0.12	0.10	0.0	0.0
0.05	0.08	0.07	0.00							

LIFT DATA										
LRPT	SIBR	DLTR	RTH	ERAD	SIBR	DLTR	STRT	ENST	ALST	RIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	0.50	0.10	00	3.00

USE THESE COEFFICIENTS FROM GIVEN SNYDER COEFFICIENTS AND 10-20 OR ADD 0.4-5.0 INTERVALS

HYDROGRAPH ROUTING

THYD5	THYD6	LAG	WASK	Y	ISR	STPA	LEPA
1	0	0	0.000	0.000	0.000	0	1
LAG	6 HOUR	24 HOUR	72 HOUR	TOTAL VOLUME			



BY W.C. DATE July 21  
 CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
 SUBJECT DECIDE LEAT BANK

**LOUIS BERGER & ASSOCIATES INC.**

SHEET 2 OF 2  
 PROJECT 1070

PEAK FLOW AND STORAGE VOLUME OF PEAK FLOW SUMMARY FOR THE PEAK FLOW-RATED PORTION OF DAM WITH  
 FLOOD IN CUBIC FEET PER SECOND (CFS) DESIGN FLOOD STORAGE  
 AREA IN SQUARE FEET (SQ. FT.)

OPERATION	STATION	AREA	PLAN RATIO	1	RAISED APPLIED TO FLOOD
				0.05	
HYDROGRAPH AT	3	18 50	1	289	
	(	47 91)	(	8 18)	
ROUTED TO	4	18 50	1	289	
	(	47 91)	(	8 18)	

**SUMMARY OF DAM SAFETY ANALYSIS**

	ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM			
	707.00	707.00	707.00	719.00			
	0	0	0	3			
	0	0	0	752			
INITIAL	707.00	MAXIMUM	MAXIMUM	DEPARTURE	DEPTH	HEIGHT	
OF	707.00	STORAGE	OUTFLOW	OVER TOP	MAX. FLOOD	FAILURE	
THE	707.00	AT 15	CFS	FOOT	FOOT	FOOT	
0.05	707.00	0	289	0.00	3.50	0.00	

DATE  
FILMED  
-8